ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalkunte
Street ID	**Street Name**	**Significant Landmark**
W0154, W0162, W0121	NA	BYRAVESWARA CIRCLE
Segment No.	**Total Length (m)**	
14/S-W0177/S105830	90.79	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	60.0	77.496003	13.003353	77.495730	13.002582	W177	W0141
2	10.86	77.495805	13.003617	77.495899	13.003583	W0177	W0141
3	20.62	77.495770	13.004019	77.495282	13.002477	W0177	DE

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvement to drain at near byraveswara circle 4th 5th cross roads	2000000	2017
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Drain work	
Tender	**Work Details**	**Job No. / Work Code**
Not Tender	Drain work	014-17-000035
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/DD/WO/126/2017-18	21/06/2017	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
21/06/2017	20/09/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9743188999		

ld Inspection Details

Number of Trees	Any Other Information	Name
0		Manjunath
Date of Inspection	**Remarks**	
25/05/2017		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	VIJAY KUMAR	25/05/2017	24/06/2017	COMPLETED
EE	SESHADRI	25/05/2017	24/06/2017	COMPLETED
AEE	RANGASWAMY	25/05/2017	24/06/2017	COMPLETED
AE	MANJUNATH	25/05/2017	24/06/2017	COMPLETED
AE	MANJUNATH	25/05/2017	24/06/2017	COMPLETED

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalkunte **Street ID:**